



AVIA PROPELLER Ltd.

Beranových 666, 199 00 Praha - Letňany, Czech Republic

INFORMATION BULLETIN

No. v 510AG/3b

Refers to: Aircraft propellers of the „V 510AG Propeller Operator´s, Installation and Maintenance Manual“. The data have been changed in the sections „Airworthiness Limitations“, “Consumable materials”, “Adjustment of the end stop of maximum governed propeller speed” and “Inspection of propeller after impact”.

Reason: Based on the results of long-term tests performed as well as of the service experience collected.

Measures: Users discard from the „V 510AG Propeller Operator´s, Installation and Maintenance Manual“ the following pages:

061	- List of amendments	page 1
061	- List of effective pages	page 1,2,3,4
061	- Contents	page 1
061.00.10	- Contents	page 1,2
061.00.10	- Airworthiness limitations	page 15, 16
061.00.10	- Check on securing	page 302
061.00.10	- Adjustment of the end stop of maximum governed propeller speed	page 509
061.10.00	- Inspection of propeller after impact	page 603, 604, 605, 606

and insert new pages dated March 20, 1998 enclosed to this bulletin:

061	- Airworthiness limitations	page 1,2
061	- List of amendments	page 1
061	- List of effective pages	page 1,2,3,4
061	- Contents	page 1
061.00.10	- Contents	page 1,2
061.00.10	- Check on securing	page 302
061.00.10	- Adjustment of the end stop of maximum governed propeller speed	page 509
061.00.30	- Consumable materials	page 1, 2
061-10-00	- Inspection of propeller after impact	page 603, 604

To be Carried Out: By the user.

Costs: No costs arise.

Material: New pages enclosed to this bulletin.

Bulletin Effective: By the date of approval.

Date: May 30, 1998

.....
Sebastian Demarteau
.....
President and CEO of AHSA Ltd.

.....
Josef Sviták
.....
Technical Director of AHSA Ltd.

.....
Igor Brunclik m. p.
.....
Commercial Director of AHSA Ltd.

.....
Pavel Kulovaný m. p.
.....
Chief Designer of AHSA Ltd.

From the technical point of view approved by CAA TI CR.